

CRANK ELECTRODES - COLD FORMED


FEATURES AND SPECIFICATIONS

- Very strong bend electrodes for higher force applications
- Bent & Offset electrodes are for hard to reach locations
- Long lasting heavy duty electrodes


- Works with all industry standard holders
- Use with 4 & 5 R.W.M.A Holders
- Bent dimensions are for reference only

- Electrical conductivity up to 85% IACS for cold formed crank electrodes
- Rockwell hardness up to 83 HRB for cold formed crank electrodes


CRANK ELECTRODES - COLD FORMED




16-38661 RWMA CLASS 2
COLD FORMED*




16-38666 RWMA CLASS 2
COLD FORMED*




16-3870 RWMA CLASS 2
COLD FORMED*




16-3871 RWMA CLASS 2
COLD FORMED*




16-38351 RWMA CLASS 2
COLD FORMED*



16-38352 RWMA CLASS 2
COLD FORMED*



16-38353 RWMA CLASS 2
COLD FORMED*



*Optional materials RWMA CLASS 1 and CLASS 3 available on special order

CRANK ELECTRODES - CASTINGS, FORGED


FEATURES AND SPECIFICATIONS

- Very strong bend electrodes for higher force applications
- Offset electrodes are for hard to reach locations
- Long lasting heavy duty electrodes


- Can be used in many job shop applications
- Works with all industry standard holders
- Use with 4 & 5 R.W.M.A Holders

- Electrical conductivity up to 80% IACS for castings & forged crank electrodes
- Rockwell hardness up to 70 HRB for castings & forged crank electrodes


CRANK ELECTRODES - CASTING, FORGED




16-3835 RWMA CLASS 2
CASTING




16-3836 RWMA CLASS 2
CASTING




16-3837 RWMA CLASS 2
CASTING




16-3838 RWMA CLASS 2
CASTING




RWMA CLASS 2
FORGED



RWMA CLASS 2
FORGED



16-3873 RWMA CLASS 2
CASTING




16-3874 RWMA CLASS 2
CASTING

SPADE ELECTRODES


- See page 6 for
Metric Conversions
- See page 7 for
Taper Dimensions




Bent Dimensions for Reference Only




Bent Dimensions for Reference Only




Bent Dimensions for Reference Only




Bent Dimensions for Reference Only



Bent Dimensions for Reference Only




Bent Dimensions for Reference Only




*Optional material available on special order: RWMA CLASS 1 and CLASS 3

GUN ELECTRODES




16-3820 RWMA CLASS 2
CASTING



16-3821 RWMA CLASS 2
CASTING




Bent Dimensions for Reference Only



16-3840 & 16-3841 RWMA CLASS 2
COLD FORMED*




Bent Dimensions for Reference Only



16-3847 RWMA CLASS 2
COLD FORMED*

*Optional material RWMA CLASS 1 and CLASS 3 available on special order.



16-382120 RWMA CLASS 2
CASTING

- See page 6 for
Metric Conversions
- See page 7 for
Taper Dimensions